


## Spare parts // Glas inserts for industrial thermometers



*Please notice: The required order specification is written on the backside of the glass insert.  
Spare glass inserts include required mounting parts.*

Order code						
<b>Type</b>						
Straight	174					
	291					
	271					
Angle 90°	175					
	292					
	272					
Angle 135°	176					
	293					
	273					
<b>Immersion tube type</b>						
For thermometers with male thread B	2					
For thermometers with union nut Da	3					
For thermometers with union nut Dc	5					
<b>Display ranges</b>						
-30...50 °C		35				
0...60 °C		06				
0...100 °C		10				
0...120 °C		12				
0...160 °C		16				
0...200 °C		20				
<b>Scale</b>						
Celsius °C				1		
Celsius and Fahrenheit (°C + °F)				2		
<b>Thermometric liquid</b>						
Standard blue fluid for display ranges up to 0...250 °C					1	
<b>Immersion tube fitting lengths (l1 or l3 corresponding to the complete machine thermometers)</b>						
<b>For types B with male thread</b>						
30 mm						030
40 mm						040
63 mm						063
100 mm						100
160 mm						160
250 mm						250
<b>For types Da with union nut G½ or G¾</b>						
89 mm / 93 mm						089
126 mm / 130 mm						126
186 mm / 190 mm						186
276 mm / 280 mm						276
426 mm / 430 mm						426
<b>For types Dc with union nut M24 x 1.5</b>						
155 mm						155
215 mm						215
275 mm						275
295 mm						295
355 mm						355
415 mm						415
<b>Example article number</b>	<b>174</b>	<b>2</b>	<b>35</b>	<b>1</b>	<b>1</b>	<b>030</b>